



## RELEASE NOTES

### Xirrus AOS

System Release 8.7.0 Rev E



## **Reservation of Rights**

Cambium reserves the right to make changes to any products described herein to improve reliability, function, or design, and reserves the right to revise this document and to make changes from time to time in content hereof with no obligation to notify any person of revisions or changes. Cambium recommends reviewing the Cambium Networks website for the latest changes and updates to products. Cambium does not assume any liability arising out of the application or use of any product, software, or circuit described herein; neither does it convey license under its patent rights or the rights of others. It is possible that this publication may contain references to, or information about Cambium products (machines and programs), programming, or services that are not announced in your country. Such references or information must not be construed to mean that Cambium intends to announce such Cambium products, programming, or services in your country.

## **Copyrights**

This document, Cambium products, and 3<sup>rd</sup> Party software products described in this document may include or describe copyrighted Cambium and other 3<sup>rd</sup> Party supplied computer programs stored in semiconductor memories or other media. Laws in the United States and other countries preserve for Cambium, its licensors, and other 3<sup>rd</sup> Party supplied software certain exclusive rights for copyrighted material, including the exclusive right to copy, reproduce in any form, distribute and make derivative works of the copyrighted material. Accordingly, any copyrighted material of Cambium, its licensors, or the 3<sup>rd</sup> Party software supplied material contained in the Cambium products described in this document may not be copied, reproduced, reverse engineered, distributed, merged or modified in any manner without the express written permission of Cambium. Furthermore, the purchase of Cambium products shall not be deemed to grant either directly or by implication, estoppel, or otherwise, any license under the copyrights, patents or patent applications of Cambium or other 3<sup>rd</sup> Party supplied software, except for the normal non-exclusive, royalty free license to use that arises by operation of law in the sale of a product.

## **Restrictions**

Software and documentation are copyrighted materials. Making unauthorized copies is prohibited by law. No part of the software or documentation may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, without prior written permission of Cambium.

## **License Agreements**

The software described in this document is the property of Cambium and its licensors. It is furnished by express license agreement only and may be used only in accordance with the terms of such an agreement.

## **High Risk Materials**

Cambium and its supplier(s) specifically disclaim any express or implied warranty of fitness for any high-risk activities or uses of its products including, but not limited to, the operation of nuclear facilities, aircraft navigation or aircraft communication systems, air traffic control, life support, or weapons systems ("High Risk Use").

This product is not restricted in the EU. Any High Risk is unauthorized, is made at your own risk and you shall be responsible for any and all losses, damage or claims arising out of any High-Risk Use.

# Contents

---

Contents .....	3
NEW FEATURES .....	4
Fixed Problems .....	5
Known Issues .....	6
Limitations and Conditions .....	8
Hardware and Software Requirements .....	10
Cambium Networks .....	12

## NEW FEATURES

---

No new features are added in this release.

## Fixed Problems

---

This section lists the fixed issues in this release:

Tracking	Description
AOS-1009	With AOS 8.7.0-8173 the exported AP configuration files now contain masked passwords, causing importing files to change passwords to "*****".
AOS-999	Xirrus AOS APs showing as "offline" in cnMaestro.
AOS-973	XR-4836 reboots after upgrade to AOS 8.5.11.
FLCN-12903	Improved roaming between Xirrus AOS APs and Wi-Fi 6/6E APs with Easypass portals.

# Known Issues

This section lists the known issues in this release:

Tracking	Description
33141, 33399	Clients associated with 802.11 AC Wave 1 APs with arp-filter proxy configured are unable to IPv6 ping each other.
33398	802.11 AC Wave 1 APs with arp-filter set to the proxy are rebroadcasting ARP request packets from wireless clients.
33595/AOS-262	(XR620) When the RF-Monitor is in Timeshare mode and Dot11g-only is on, beacons are sent at a data rate of 1 Mbps rather than 6 Mbps.
33663	On 802.11 AC Wave 1 APs, stations may get disassociated due to a radio reset. The Syslog shows "Low activity condition detected on IAP iap1. Resetting IAP."
33821	EAP stations may stop passing traffic until the client re-associates.
33827/AOS-399	EAP clients on wave2 APs may stop passing traffic until the client re-associates.
33833	XD2-230 may send unnecessary CTS packets when 802.11g devices are present in the environment.
33851	Some stations are unable to pass traffic when MU-MIMO is enabled.
33878	Beacon Intervals and RSSI levels on 802.11 AC are not consistent in 2.4 GHz.
33893	On 802.11 AC Wave 2 APs, changing the 802.11k (Radio Resource Management) in global settings doesn't take effect until after a reboot.
33896	802.11r capable iPads are not able to associate with an SSID when 802.11r (fast roaming) and .11w (Protected Management Frames) are enabled.
33924	Stations connected to Wave 2 APs occasionally can't pass traffic. On the station, turning Wi-Fi off and on will fix the problem.
33926	WDS Link recovery is slow on Wave 2 APs after replacing a WDS client or host AP - it takes a long time to re-establish a WDS link. After the configuration of the new unit is complete, reboot the APs on both sides of the link to prevent this delay.
AOS-208, AOS-223	Hotspot Shield, Psiphon, and Ultrasurf cannot be detected reliably.
AOS-316, 33998	Some clients on Wave 1 APs with a bonded channel of 40 MHz may not rate back up past 81.0 Mbps. A de-authentication of the client clears this condition.
AOS-337, 33817	On 802.11 AC Wave 2 APs, stations may get disassociated due to a radio reset. The Syslog shows "Low activity condition detected on IAP iap2. Resetting IAP".
AOS-360, 34053, 34059	Management Engine Restarts occur.
AOS-389	Multiple XR-620s (running AOS 8.4.9) are experiencing network connectivity loss. Rebooting fixes this, but it may recur.

Tracking	Description
AOS-412	XD2-240 shows WDS Link as 11an when both sides are 11anac capable.
AOS-419	Watchdog triggers errors on XR-2000/4000 series AP after upgrading to AOS 8.5.5, due to the processing of large numbers of unassociated stations.
AOS-437	When WDS is configured, a SYSLOG message is generated that should be ignored - the problem it refers to has been fixed in AOS 8.5.6. After an AP reboot, ignore this message: "CTaskMacRcv(3710) taking lapRdLock(7) lock @mib.cpp:getEntry:7369 out of order holding: stationMutex(18)".
AOS-656	<p>When Station moves from EasyPass Portal SSID to SSID configured for WPA/2 PSK, for the first time the end User enters the passphrase they will get an "Invalid Password" message on their device.</p> <p>Recommendation - Cancel out and reconnect to the SSID again, then re-enter the passphrase and it will work.</p>
AOS-725	Unrealistic RX IAP stats values are occasionally being displayed. Many times on refresh it does re-display correctly.
AOS-727	APs are not passing Username/VLAN assignment/User Group when WPR STA is roaming.
AOS-739	Email syslogging does not email any syslogs.
AOS-742	mDNS traffic for airplayit service is not being passed from the wired side to the wireless on.
AOS-743	Running powerup autochannel on 802.11ac wave-2 AP does not change the channel on 2.4 GHz radio.
AOS-752	Using XD2-230 APs, users occasionally experience client connectivity issues with AOS version 8.5.7 or higher due to decryption errors.

# Limitations and Conditions

This section lists the Limitations and Conditions in this release:

Tracking	Description
30392	Bonjour – AppleTV is not able to service a client on SSID with VLAN when AppleTV is on the Bridged wired network. It is not recommended that you place AppleTV on the Bridged Management LAN segment. This will cause a lot of multicast traffic to be processed by the Array on the Management VLAN and can affect the performance of the Array. Isolation of Multicast Traffic is recommended to be handled in VLANs that are not part of the Array Management VLAN.
33828	When there are many stations associated with radio1 on an XD2-230, they are experiencing poor performance, high ping loss and delay, and video freezes. This occurs on adjacent 5GHz channels which are not recommended. Correct channel separation is recommended and when this occurs performance degradation will not occur.
34006	iPad Air (first generation) cannot associate with channels 140 or 144 on 802.11 AC Wave 2 APs platforms. Later generations do not have this problem.
AOS-295, 33974	802.11u, and Hotspot 2.0 are not available on 802.11 AC Wave 2 APs, and they cannot be enabled.
AOS-617	WPA2/Radius Mac Encryption/Authentication option. This is not available on the XMS-C profile setting. Here is a cli snippet that can be used from XMS-cloud: <ul style="list-style-type: none"><li>• ssid edit KJD-RadiusMAC_PSK</li><li>• encryption wpa2 unique-settings</li><li>• passphrase 1234567890</li><li>• psk on</li><li>• auth radius-mac</li></ul>
AOS-772	SSID containing a backslash character may not be handled correctly by XMS-cloud.
AOS-713	Aeroscout/Stamley will disable the timeshare monitor on the same radio/IAP as the wifi-tags are enabled.

- **WDS:** When doing a software upgrade, WDS client (remote) APs must be upgraded before WDS host (network-connected) APs. XMS-cloud will not automatically apply upgrades in this order for you.
- **WDS:** Using WDS between different families of APs (e.g., WDS between an XD AP and an XR AP, or between Wave 1 and Wave 2 XD APs) is not recommended. If you must create a link between different radio types, set the most advanced AP type as the host.
- **External WPR (PAP to CHAP)**



Found that using CHAP has to have two lines uncommented in the .cgi file. These two work with Windows 2012 R2 NPS/IIS server.

wpr.cgi

Uncomment Line 13:

```
line 9 - # NOTE: If printf is not installed on the server, md5sum will fail. In
that
line 10 - # case, uncomment the line directly below, comment out the mdsum calls,
and
line 11 - # uncomment the md5 & md5_hex calls.
line 13 - # use Digest::MD5 qw(md5 md5_hex md5_base64); <--- was
line 13 - use Digest::MD5 qw(md5 md5_hex md5_base64); <--- needs to be
```

Second change:

**Was:**

```
Line 135 - if ($userpassword == CHAP) {
Line 136 - $passvar = 'response=' . md5sum("\0" . $password . $newchal);
Line 137 - # $passvar = 'response=' . md5_hex("\0" . $password . $newchal);
```

**Change To:**

```
Line 135 - if ($userpassword == CHAP) {
Line 136 - # $passvar = 'response=' . md5sum("\0" . $password . $newchal);
Line 137 - $passvar = 'response=' . md5_hex("\0" . $password . $newchal);
```

Once this was changed then CHAP started to work.

# Hardware and Software Requirements

- XI-AC3470 is equipped with 4 Tx chains, Rx chains, and 4 spatial streams. Depending on the Access Point capacity, the AOS will automatically configure each radio module to obtain optimal functionality. The table below lists different operating modes based on the HD modular AP and the number of radios installed.
- Wave 2 Radio Module Operating Modes.

Model	Tx Chains	Rx Chains	Streams	Tx power per radio	
XR-2247	4	4	4	No Tx power restrictions	
XR-2447	3	4	3	Mon + 5G + 5G + 2.4G	13 dBm(default)
				5G + 5G + 5G + Mon	12 dBm
				5G + 5G + 5G + 5G	12 dBm
				5G + 5G + 5G + 2.4G	13 dBm
				5G + 5G + 2.4G + 2.4G	14 dBm
				5G + 2.4G + 2.4G + 2.4G	15 dBm
XR-4447	4	4	4	No Tx power restrictions	
XR-4847	4	4	4	No Tx power restrictions	
XR-6847	4	4	4	Mon + 2 2.4G + 5 5G	18 dBm (default)
				All configurations + Mon	18 dBm
				All radios with no Mon	No Tx power restrictions
XR-7247	4	4	4	Mon + 3 2.4G + 8 5G	18 dBm (default)
				All configurations + Mon	18 dBm
				All radio with no Mon	No Tx power restrictions
XR-7647	4	4	4	Mon + 3 2.4G + 12 5G	12 dBm (default)
				Mon + 2 2.4G + 13 5G	10 dBm
				Mon + 1 2.4G + 14 5G	8 dBm
				Mon + 15 5G	6 dBm

- Wave 2 Radio Module Upgrade Configurations. The table below summarizes power requirements and configurations for installing XI-AC3470 radios in an XR modular AP.

Model Series	Upgraded Model No	# Radios after Upgrade	Which Slots to Use (RF Slot #s)	Watts / Injector Models
XR-2000	XR-2247	2	0, 2	30W, PoE+ XP1-MSI-30, XP1-MSI-75M, XP8-MSI-70M, XT-5024/5048
XR-2000	XR-2447	4	All slots	40W XP8-MSI-70M, XP1-MSI-75/75M
XR-4000	XR-4447	4	1, 3, 5, 7	75W XP8-MSI-70M, XP1-MSI-75/75M
XR-4000	XR-4847	8	All slots	75W XP1-MSI-75/75M
XR-6000	XR-6847	8	0, 2, 4, 6, 8, 10, 12,14	95W XP2-MSI-95M (one port)
XR-7000	XR-7247	12	0, 1, 2, 4, 5, 6, 8, 9,10, 12,13,14	95W XP2-MSI-95M (two ports)
XR-7000	XR-7647	16	All Slots	95W XP2-MSI-95M (two ports)

# Cambium Networks

---

Cambium Networks delivers wireless communications that work for businesses, communities, and cities worldwide. Millions of our radios are deployed to connect people, places and things with a unified wireless fabric that spans multiple standards and frequencies of fixed wireless and Wi-Fi, all managed centrally via the cloud. Our multi-gigabit wireless fabric offers a compelling value proposition over traditional fiber and alternative wireless solutions. We work with our Cambium certified ConnectedPartners to deliver purpose built networks for service provider, enterprise, industrial, and government connectivity solutions in urban, suburban, and rural environments, with wireless that just works.

User Guides:	<a href="http://www.cambiumnetworks.com/guides">http://www.cambiumnetworks.com/guides</a>
Technical training:	<a href="http://www.cambiumnetworks.com/technical_training">http://www.cambiumnetworks.com/technical_training</a>
Support website:	<a href="https://support.cambiumnetworks.com">https://support.cambiumnetworks.com</a>
Main website:	<a href="http://www.cambiumnetworks.com">http://www.cambiumnetworks.com</a>
Sales enquiries:	<a href="mailto:solutions@cambiumnetworks.com">solutions@cambiumnetworks.com</a>
Support enquiries:	<a href="https://support.cambiumnetworks.com">https://support.cambiumnetworks.com</a>
Telephone number list:	<a href="http://www.cambiumnetworks.com/contact-us/">http://www.cambiumnetworks.com/contact-us/</a>
Address:	Cambium Networks Limited, Unit B2, Linhay Business Park, Eastern Road, Ashburton, Devon, TQ13 7UP United Kingdom



Cambium Networks and the stylized circular logo are trademarks of Cambium Networks, Ltd. All other trademarks are the property of their respective owners.

© Copyright 2023 Cambium Networks, Ltd. All rights reserved.